



PRODUCT BULLETIN

DATE: December 1, 2005

PRODUCT: DataFX Cell Monitor, P/N 121711-004 and 121711-CMM

SUBJECT: Obsolescence of P/N 121788-001 Current Sensor

CONTACT: Scott Marvel, tel. +1 949 829 8264, fax. +1 949 829 8394, email: smarvel@christieCBS.com

The UK supplier of the DataFX Current Sensor p/n 121788-001 has stopped production of this item and is offering no suitable replacement. Christie Engineering has performed extensive research into other possible suppliers of an inductive current sensor which would be compatible with the DataFX, and has determined there is no acceptable replacement available at this time.

Therefore, we have recommended the p/n 121788-001 Current Sensor be replaced with an external current sensing shunt and harness assembly. This will require a modification to the DataFX main circuit board, so any units in the field would need to be returned to us for modification. This will represent an improvement to the DataFX current metering capability, providing superior accuracy and reliability.

At this time, the modification kit is being finalized, and will be assigned a part number and unit cost for all DataFX users. All existing DataFX units can continue to be used with the original current sensor, but in the event the sensor fails, the DataFX itself will need to be shipped to us for modification, and the external current sensing shunt and harness assembly would need to be purchased.

Thanks for your continued use of Christie equipment! We will release more detailed information shortly.

20381 Lake Forest Drive, Suite B3, Lake Forest, California USA 92630
Tel. +1 949 829 8264, Fax. +1 949 829 8394, www.christieCBS.com