

DataFX Service Information Letter

February 18, 2009

Subject: New Current Sensor

This is the latest DataFX current sensor p/n 125000-001 included with all new DataFX units. This current sensor is compatible with the RF80-K or U-60 models, but not with the older RF80JH or G/T models.

The older style clamp-on inductive current sensor is no longer available and can be replaced by this new sensor for use with the RF80-K or U-60.

